



# Rock Creek Culvert



## Past Week:

Ahtna Environmental Inc. worked with their subcontractor, CLI, to mobilize equipment to the job site as well as some concrete barriers. Ahtna also started their subcontractor, Premier Construction Survey, off with some preliminary survey work.



Above: Grubbing at Rock Creek Culvert

## This Week:

Ahtna Environmental, Inc. with their subcontractor, CLI, began grubbing the construction site at Rock Creek Culvert. They also established their traffic control, and their Quality Control. The survey subcontractor, Premier Construction Survey, began slope staking the construction site at Rock Creek Culvert, as well as some survey work at the MP 5 Culvert.

Below: Outlet at MP 5 pipe



Project Engineer: Nathan Jones  
Construction Inspectors:  
Bob Hammond  
Walter Graham